


ARDUINO CNC SHIELD NANO



The **Arduino CNC Shield** is a popular expansion board designed to control CNC (Computer Numerical Control) machines, such as 3D printers, laser cutters, or engravers. When paired with an **Arduino Nano**, it provides a compact and cost-effective solution for controlling stepper motors and other peripherals in CNC applications.

Here's a breakdown of the **Arduino CNC Shield** and how it works with the **Arduino Nano**:

Key Features of the Arduino CNC Shield

1. **Stepper Motor Control:**
 - Supports up to 4 stepper motors (X, Y, Z, and A axes).
 - Uses **A4988** or **DRV8825** stepper motor drivers (inserted into the shield).
2. **Spindle/Laser Control:**
 - PWM output for controlling a spindle or laser module.
 - Can be used for speed control or on/off functionality.
3. **Endstops:**
 - Dedicated pins for connecting endstops (limit switches) for each axis.
 - Helps in homing and preventing over-travel.
4. **Coolant Control:**

ARDUINO CNC SHIELD NANO

- Optional control for coolant systems (e.g., mist or flood coolant in milling machines).
 - 5. **Compact Design:**
 - Designed to stack on top of an Arduino Uno, but can also be adapted for use with an Arduino Nano.
-

Using the CNC Shield with an Arduino Nano

The CNC Shield is typically designed for the Arduino Uno, but with some modifications, it can work with an Arduino Nano. Here's how:

1. **Pin Compatibility:**
 - The Nano has a different pin layout compared to the Uno, so you'll need to ensure proper connections.
 - Use jumper wires or a custom adapter to connect the Nano to the CNC Shield.
 2. **Power Supply:**
 - The CNC Shield can be powered via the Arduino Nano's VIN pin or directly through the shield's power terminals.
 - Ensure the voltage matches the stepper motor drivers and motors (typically 12V or 24V).
 3. **Firmware:**
 - Use CNC firmware like **Grbl** (for G-code interpretation) or custom Arduino sketches.
 - Grbl is a popular choice for CNC control and can be uploaded to the Nano.
 4. **Wiring:**
 - Connect the stepper motors to the appropriate driver slots (X, Y, Z, A).
 - Connect endstops to the dedicated endstop pins.
 - Connect the spindle/laser and coolant control pins if needed.
-

Steps to Set Up an Arduino Nano with the CNC Shield

ARDUINO CNC SHIELD NANO

1. **Upload Grbl to the Nano:**
 - Download the Grbl library from the official GitHub repository.
 - Use the Arduino IDE to upload Grbl to the Nano.
 2. **Connect the CNC Shield:**
 - Wire the Nano to the CNC Shield, ensuring proper pin mapping.
 - Insert the stepper motor drivers (A4988 or DRV8825) into the shield.
 3. **Configure Grbl:**
 - Use a serial monitor or a Grbl controller software (e.g., Universal G-code Sender) to configure the settings.
 - Set parameters like steps per millimeter, acceleration, and max speed.
 4. **Test the Setup:**
 - Connect your CNC machine (stepper motors, spindle, etc.).
 - Send G-code commands to test the movement and functionality.
-

Advantages of Using an Arduino Nano

- **Compact Size:** Ideal for small CNC machines or projects with space constraints.
 - **Cost-Effective:** Cheaper than an Arduino Uno or Mega.
 - **Flexibility:** Can be adapted for various CNC applications.
-

Limitations

- **Limited Pins:** The Nano has fewer I/O pins compared to the Uno or Mega, which may limit advanced functionality.
 - **Power Handling:** The Nano may not handle high currents directly, so ensure proper power supply for motors and drivers.
-

Applications

- **3D Printers:** Control stepper motors for X, Y, and Z axes.

ARDUINO CNC SHIELD NANO

- **Laser Cutters/Engravers:** Control laser modules and XY movement.
- **PCB Mills:** Precision control for milling PCBs.
- **DIY CNC Machines:** Custom CNC projects for hobbyists.

المتطلبات:

1. Arduino Nano
2. درع CNC (CNC Shield)
3. محركات خطوية (Stepper Motors)
4. مكتبة AccelStepper

تنزيل المكتبة:

من خلال AccelStepper قبل البدء، تأكد من تثبيت مكتبة:

1. افتح Arduino IDE.
2. Sketch -> Include Library -> Manage Libraries.
3. وقم بتثبيتها AccelStepper ابحث عن.

الكود:

```
cpp
Copy
#include <AccelStepper.h>

// للمحركات الخطوية (Pins) تعريف الأطراف
#define X_STEP_PIN 2
#define X_DIR_PIN 5
#define Y_STEP_PIN 3
#define Y_DIR_PIN 6
#define Z_STEP_PIN 4
#define Z_DIR_PIN 7

// تعريف المحركات الخطوية
AccelStepper stepperX(AccelStepper::DRIVER, X_STEP_PIN, X_DIR_PIN);
AccelStepper stepperY(AccelStepper::DRIVER, Y_STEP_PIN, Y_DIR_PIN);
AccelStepper stepperZ(AccelStepper::DRIVER, Z_STEP_PIN, Z_DIR_PIN);

void setup() {
    // تعيين السرعة القصوى والتسارع لكل محرك
    stepperX.setMaxSpeed(1000);
    stepperX.setAcceleration(500);
```

ARDUINO CNC SHIELD NANO

```
stepperY.setMaxSpeed(1000);
stepperY.setAcceleration(500);

stepperZ.setMaxSpeed(1000);
stepperZ.setAcceleration(500);

// تحريك المحركات إلى مواضع محددة
stepperX.moveTo(1000); // خطوة X 1000 تحريك المحرك
stepperY.moveTo(500); // خطوة Y 500 تحريك المحرك
stepperZ.moveTo(200); // خطوة Z 200 تحريك المحرك
}

void loop() {
// تشغيل المحركات
if (stepperX.distanceToGo() != 0) {
  stepperX.run();
}

if (stepperY.distanceToGo() != 0) {
  stepperY.run();
}

if (stepperZ.distanceToGo() != 0) {
  stepperZ.run();
}
}
```

شرح الكود:

1. تعريف الأطراف (Pins):

- والتي تتصل بدرع (X, Y, Z) يتم تعريف الأطراف الخاصة بالمحركات الخطوية CNC.

2. تعريف المحركات الخطوية:

- لإنشاء كائنات لكل محرك خطوي AccelStepper يتم استخدام مكتبة.

3. الإعداد (Setup):

- يتم تعيين السرعة القصوى والتسارع لكل محرك.
- moveTo() يتم تحريك المحركات إلى مواضع محددة باستخدام.

4. الحلقة الرئيسية (Loop):

- run() يتم تشغيل المحركات باستخدام