

✳️ PROSKIT 8PK-366D شفط

✏️ المواصفات التفصيلية:

لإزالة اللحام من على اللوحات الإلكترونية (Pump Sucker) نوع شفط: شفط معدني

المواد والتصميم

الجسم: مصنوع من الألومنيوم عالي الجودة، مما يضمن المتانة وخفة الوزن

النوابض: مزود بنابض فولاذي مقاوم للصدأ لضمان قوة امتصاص عالية

رأس القلع-كش: رأس مقاوم للحرارة وقابل للاستبدال، مصنوع من مادة تفلون لضمان عمر طويل وكفاءة عالية

الأبعاد:

الطول: 163 ملم

القطر: 18 ملم

الوزن: حوالي 86.27 جرام

المواصفات الفنية:

قوة الامتصاص: 30 سم-زئبق، مما يضمن إزالة فعّالة لقطرات اللحام

المميزات الإضافية:

سهولة الصيانة: تصميم يسمح بتنظيف الرأس بسهولة بعد الاستخدام

مناسب لمجموعة متنوعة من التطبيقات: مثالي لإزالة اللحام من اللوحات الإلكترونية، بما SMD و DIP في ذلك

تصميم مريح: مقبض مريح يضمن سهولة الاستخدام والتحكم أثناء العمل

التطبيقات:

إزالة اللحام من اللوحات الإلكترونية أثناء عمليات الإصلاح والتعديل

إعادة استخدام المكونات الإلكترونية عن طريق إزالة اللحام بعناية

تنظيف اللوحات الإلكترونية قبل إعادة لحام المكونات الجديدة

PROSKIT 8PK-366D لماذا تختار شفط ؟

جودة عالية: مصنوع من مواد متينة تضمن عمراً طويلاً وأداءً مستقرًا

سهولة الاستخدام: تصميم مريح يضمن استخدامًا مريحًا ودقة في العمل

فعالية ممتازة: قوة امتصاص عالية تضمن إزالة فعّالة لقطرات اللحام

تعدد الاستخدامات: مناسب لمجموعة واسعة من تطبيقات إزالة اللحام في مجال

To desolder the iron plastic part from a **Pro'sKit 8PK-366D** soldering iron, follow these steps carefully:

Tools Needed:

- **Soldering iron** (another one, if the 8PK-366D is damaged)
- **Desoldering pump (solder sucker) or desoldering braid (wick)**
- **Tweezers or pliers** (to handle hot plastic parts)
- **Heat gun or hairdryer** (optional, if adhesive is involved)
- **Small screwdriver** (for prying if needed)

Steps:

1. Power Off & Disconnect

- Ensure the soldering iron is **unplugged** and completely **cooled down** before working on it.

2. Inspect the Plastic Housing

- Check if the plastic part is held by screws, clips, or adhesive.
- If screws are present, remove them first.
- 3. **Apply Heat to Desolder (if needed)**
 - If the plastic part is soldered or heat-staked, gently reheat the joint with a soldering iron to soften the plastic or solder.
 - Use a **desoldering pump** or **wick** to remove excess solder.
- 4. **Pry Gently**
 - Once heated, use a **small flat screwdriver** or **tweezers** to carefully separate the plastic from the metal parts.
 - Avoid excessive force to prevent cracking the plastic.
- 5. **Check for Adhesive**
 - If the plastic is glued, use a **heat gun** (low setting) or **hairdryer** to soften the adhesive before prying.
- 6. **Clean & Reassemble (if needed)**
 - Remove any leftover solder or adhesive.
 - If reassembling, ensure proper alignment before securing.

Safety Tips:

- **Work in a well-ventilated area** (melting plastic can release fumes).
- **Wear gloves** to avoid burns from heated parts.
- **Be patient**—forcing plastic can cause irreversible damage.

