



Thermometer + Control



Specifications

- It is used to control temperature for heaters incubatoras. etc
- Input voltage: 9V dc - 15Vdc
- Output load up to 16 ampere
- Temperature range : 0 degree C to 100 degree C