

Indoor Thermometer

Model:TM1001



Specification:

1. Temperature range:
Indoor: -10 to 50 °C (14 TO 122° F)
Outdoor: -50 to 70 °C (-58 to 158 °F) (If applicable)
2. Indoor Hygrometer range:
30% RH TO 90% RH (If applicable)
3. For °C and °F conversion, push the °C/°F button. (If applicable)
4. Fix the unit on a wall indoor with a screw.
5. Use one 1.5 volt AAA battery.
6. Check the maximum and/or minimum readings by pressing the MAX/MIN button. It will show the maximum or minimum temperature and/or humidity of the period from the last reset.
7. Reset the memory by pressing the RESET button.
All the memory will be reset after battery is replaced.

Made in China