

GEAR MOTOR 3V 30RPM

Description:

Gear Motor P12 3V 30RPM runs at a speed of 30rpm. All you need to do is connect the positive and negative pole-pin, simple enough for beginners.



Specifications:

VOTAGE V	NO LOAD		At Maximum Efficiency				STALL	
	Speed RPM	Current mA	Speed RPM	Current mA	Topque Kg.cm	Out put mW	Topque Kg.cm	Current mA
2.4	55	30	40	350	0.7	280	3.0	500
6.0	70	70	52	450	1.2	640	4.0	700

MADE IN CHINA