

GEAR MOTOR 6V 50RPM

Product Description:

Gear Motor P12 6V 50RPM runs at a speed of 50rpm. All you need to do is connect the positive and negative pole-pin, simple enough for beginners.



Specifications:

VOTAGE V	NO LOAD		At Maximum Efficiency				STALL	
	Speed RPM	Current mA	Speed RPM	Current mA	Topque Kg.cm	Out put mW	Topque Kg.cm	Current mA
2.4	55	30	40	350	0.7	280	3.0	500
6.0	70	70	52	450	1.2	640	4.0	700

MADE IN CHINA