



DESOLDER IRON PLASTIC PROSKIT 908-366A

The **Pro'sKit 908-366A** is a desoldering tool, often referred to as a desoldering iron or pump, used for removing solder from electronic components and circuit boards. If you're looking for information on how to use, maintain, or troubleshoot this tool, here are some general guidelines:

Key Features of Pro'sKit 908-366A:

1. **Desoldering Pump:** It typically includes a spring-loaded suction mechanism to remove molten solder.
 2. **Heat-resistant Plastic Body:** Designed to withstand high temperatures during use.
 3. **Replaceable Tips:** Comes with interchangeable tips for different soldering/desoldering tasks.
 4. **Compact and Lightweight:** Easy to handle for precision work.
-

How to Use the Pro'sKit 908-366A:

1. **Prepare the Tool:**
 - Ensure the desoldering iron is clean and free of debris.
 - Insert the appropriate tip for your task.
2. **Heat the Solder:**
 - Power on the desoldering iron and allow it to reach the desired temperature.
 - Place the tip of the iron on the solder joint to melt the solder.
3. **Activate the Suction Pump:**
 - Once the solder is molten, press the plunger on the desoldering pump to create suction.
 - Release the plunger to draw the molten solder into the pump.



DESOLDER IRON PLASTIC PROSKIT 908-366A

4. Clear the Pump:

- After use, expel the collected solder by pressing the plunger again.
-

Maintenance Tips:

- **Clean the Tip Regularly:** Use a damp sponge or brass wool to clean the tip during and after use.
 - **Empty the Solder Chamber:** Ensure the pump is cleared of solder debris after each use to maintain optimal performance.
 - **Replace Worn Tips:** Over time, the tips may wear out and need replacement.
 - **Store Properly:** Keep the tool in a dry, cool place to avoid damage.
-

Troubleshooting Common Issues:

1. **Solder Not Suctioned Properly:**
 - Check if the tip is clean and not clogged.
 - Ensure the pump mechanism is functioning correctly.
 2. **Tool Not Heating:**
 - Verify the power connection.
 - Check for any visible damage to the heating element.
 3. **Plastic Body Overheating:**
 - Avoid prolonged use at high temperatures.
 - Allow the tool to cool down between uses.
-

Safety Precautions:

- Always work in a well-ventilated area to avoid inhaling solder fumes.

DESOLDER IRON PLASTIC PROSKIT 908-366A

- Wear safety glasses to protect your eyes from solder splashes.
- Handle the desoldering iron with care to avoid burns.

