

# Variable transformer

## 1000 VA



### SPECIFICATIONS:

- |                       |               |
|-----------------------|---------------|
| 1- Input :            | 220 VAC       |
| 2- Output :           | 0 ~ 250 VAC   |
| 3- Temperature range: | -15°C ~ +40°C |
| 4- Maximum humidity:  | 90%RH @ 25°C  |
| 5- Weight :           | 6,1kg         |
| 6- Analog Volt Meter  |               |

Made in China