

Digital WOOD MOISTURE METER UNI-T UT377

جهاز قياس رقمي مصمم لقياس محتوى الرطوبة في الخشب -
والورق والخشب الرقائقي والمواد الخشبية الأخرى.

The **UNI-T UT377A** is a digital wood moisture meter designed to measure the moisture content in wood and other building materials. It's a handy tool for professionals and DIY enthusiasts who need to ensure the proper drying and quality of wood, which is crucial for construction, woodworking, and flooring applications.



Key Features of the UNI-T UT377A:

1. **Moisture Measurement Range:**
 - Typically measures moisture content in wood from **5% to 50%** (exact range may vary, so check the specifications).
2. **Material Compatibility:**
 - Primarily designed for wood but can also measure moisture in other materials like drywall, concrete, and masonry (depending on the model and settings).
3. **Pin-Type Design:**
 - Uses pins or probes that penetrate the wood surface to measure moisture content. This provides accurate readings by measuring the electrical resistance between the pins.
4. **LCD Display:**
 - Features a clear, easy-to-read LCD screen that shows moisture levels in percentage.
5. **Auto Power Off:**
 - Helps conserve battery life by automatically turning off after a period of inactivity.
6. **Portable and Lightweight:**



Digital WOOD MOISTURE METER UNI-T UT377

- Compact design makes it easy to carry and use on-site.
- 7. **Battery Powered:**
 - Usually powered by a 9V battery, which is included or sold separately.
- 8. **Calibration:**
 - Some models may offer calibration options to ensure accurate readings over time.

Applications:

- **Woodworking:** Ensuring wood is properly dried before use.
- **Construction:** Checking moisture levels in building materials to prevent mold or structural issues.
- **Flooring Installation:** Verifying that wood flooring has the correct moisture content to avoid warping or gaps.
- **Firewood:** Checking if firewood is dry enough for efficient burning.

How to Use:

1. Insert the pins into the wood surface.
2. Turn on the device and wait for the reading to stabilize.
3. Read the moisture percentage on the LCD display.
4. Compare the reading to the recommended moisture levels for your specific application.

Tips for Accurate Measurements:

- Ensure the pins are fully inserted into the wood.
- Take multiple readings in different areas for consistency.
- Avoid measuring near the edges or ends of the wood, as these areas may have different moisture levels.



Digital WOOD MOISTURE METER UNI-T UT377

Limitations:

- Pin-type meters like the UT377A leave small holes in the wood, which may not be ideal for finished surfaces.
- Accuracy can be affected by the wood species, temperature, and surface conditions.